

Figure D-19. Comprehensive Environmental Response, Compensation, and Liability Act sign at TRA-Y Brass Cap Area (PN02274-2-1).



Figure D-20. View of polychlorinated biphenyl spill at TRA-6I9 looking west with Comprehensive Environmental Response, Compensation, and Liability Act sign (PN02274-2-13).




Figure D-21. Comprehensive Environmental Response, Compensation, and Liability Act sign at polychlorinated biphenyl spill at TRA-626 (PN02274-2-7).



Figure D-22. Polychlorinated biphenyl spill at TRA-626 looking south (PN02274-2-8).




Figure D-23 Polychlorinated Biphenyl spill at TRA-652 looking south with Comprehensive Environmental Response, Compensation, and Liability Act sign in foreground (PN02274-1-23).




Figure D-24. Comprehensive Environmental Response, Compensation, and Liability Act sign at TRA-04, Warm Waste Retention Basin, looking south (PN02274-2-3).



Figure D-25. Comprehensive Environmental
south (PN02274-2-2).

Compensation, and Liability sign at TRA-04, Warm Waste Retention Basin, looking